

3/MGL/cwb 5750 7 Nov 1968

From: Commanding Officer

Commanding General, First Marine Division (Field Historian) To:

Subj: Command Chronology

Ref:

(a) MCO 5750.2 (b) FMFPac 5750.8 (c) DivO 5750.2B

(1) October Chronology

1. In accordance with reference (a), (b) and (c) enclosure (1) is hereby submitted.

> M. G. LILLEY By direction

5750 7 Nov 1968

COMMAND CHRONOLOGY

1 October 1968 to 31 October 1968

INDEX

PART I - ORGANIZATIONAL DATA

PART II -- NARRATIVE SUMMARY

PART III - SEQUENTIAL LISTING OF SIGNIFICANT EVENTS

PART IV - SUPPORTING DOCUMENTS

√TAB A - OFFICER ASSIGNMENTS

5750 7 Nov 1968

PART I

ORGANIZATION DATA

		ORGANIZATION DATA	
l.	DESIGNATION		COM ANDER
	7th Engineer Battalion (R	ein), FMF	LtCol T. T. ANNAS
		SUBORDINATE UNITS	
	<u>Unit</u>	Commander	RTD
	НqСо	Capt. T.D. LEWIS	8 November 1968
	ServCo	Capt. C.A. ROCCO	16 November 1968
	ConAn	lstLt. A.E. MORRISON	18 December 1968
	ConBu	Capt. M.J. ESPOSITO	4 February 1969
	$Go_{\mathfrak{A}}G_{\mathfrak{A}}$	Maj. J.T. MARSHALL	1 July 1969
	CouDu	lstLt. E. BOTELHO	18 September 1969
		ATTACHED UNITS	
	lst Bridge Co	lstIt. D.A. PEASENEIL	18 December 1968
2,	LOCATION		
	Unit	Date Arrived in Countr	<u>Location</u>
	7th Engineer Babbalion	6 August 1965	DaNang, RVN
	lst Bridge Co	3 December 1965	DaNang, RVN
3.	STAFF OFFICERS		
	Section	Officer	RTD
	Executive Officer	Major R.A. HOOK	20 November 1969
	S-3]	CWO F.A. HUFNAGEL	l January 1969
	\$-2/\$-3	Major M.G. LILLEY	7 July 1969
	S-4	Major G.S. HAMILTON	11 September 1969
	Supply Officer	2ndLt, L.E. KRUSEMARK	12 October 1969
	Sgt Maj	SgtMaj P.R. HAMBLETON	15 May 1969
		<u> 1</u>	Enclosure (1)

DECLASSIFIED

4. AVERAGE MONTHLY STRENGTH

USMC

USN

OFF ENL OFF 2

53 1,124 24

5, PERSONNEL GAINS AND LOSSES

GAINS LOSSES USN USMC USMC USN 0 13 10 0 OFF 43 33 ENL . 0

Enclosure (1)



6810

PART II

NARRATIVE SUMMARY

The 7th Engineer Battalion continued support of the III Marine Amphibious Force within the DaNang area. One platoon of the 1st Bridge Company continues to furnish tactical bridging support to the 9th Engineer Battalion at Chu Iai. On 15 October 1968 Administrative and Operational Control of the 3rd Bridge Company was passed to the 3rd Marine Division.

Company "A", 7th Engineer Battalion continues upgrading of Routes 545, 130 and 30 for class 50 traffic.

Company "B", 7th Engineer Battalion continued upgrading of Route 1 for class 50 traffic, and maintenance of Route 12 east and west.

Company "C", 7th Engineer Battalion continues upgrading of Route 540 north for class 50 traffic, and maintenance of Route 542.

Company NDE, 7th Engineer Battalion continued upgrading of Route 540 south for class 50 traffic, and maintenance of Route 4 as required.

Progress on Phase II of the DaNang Barrier continued at a slow rate due to 40.8 inches of rain falling during the month of October.

PART III

1. Topics

- a. Personnel and Administration. None
- b. Enery, weather and terrain A total of 40.8 inches of rain was recorded during the month of October.

TIME	INCIDENT	COORDINATES
O10850H	Company "D" mine sweep team found one home made whoo, blown in place.	AT 914598
021230H	Company "B" mine sweep team found one 195mm round wired to be command detonated, blown in place.	BT 069562
030915Н	Company "D" mine sweep team found one 25 lb rock mine, removed and given to 5th Marines.	AT 912507
040955H	Company "D" mine sweep team found one booby trapped jungle boot with M-26 grenade, blown in place.	AT 925518
070945Н	Company "D" mine sweep team found (2) 20 lb box mines 30 meters apart, blown in place.	AT 9346 3 2

Enclosure (1)

DECLASSIFIED

100745H	Company "C" mine sweep team found one M-26 in C-ration can, blown in place.	ΤA	944693
100830H	Company "C" mine sweep team found one box mine 15-20 lbs, blown in rice paddy.	AT	942617
100850H	Company "B" mine sweep team was involved when one 105 round was command detonated wounding 3 civilian and 2 7th Engr Bn personnel.	BT .s	053594
101030H	Service Company personnel in M-51 detonated mine. 1 USMC WIA.	ВГ	066678
111030Н	Company "D" mine sweep team while in the process of blowing two boobytraps personnel detonated a 60mm round booby trap. 2 USMC WIA.	AT	920509
111200H	Company "D" mine sweep team found one M-26 grenade booby trap, blown in place.	ΤA	917512
112315Н	Company "D" CP received 10-12 rounds of 60mm mortar fire, returned .50 cal fire.	ΤA	917580
13094011	Company "D" mine sweep team found one mine (unk type), blown in place.	TA	912505
170800H	Company "B" personnel while checking bridge detonated M-26 grenade booby trap. 1 USMC WIA.	BT	046613
141910H	lst Bridge Company personnel received small arms fire along the Song Thu Bon River from AT 935532 to AT 978547 while attempting to recover Mike Boat from down river. Returned fire and sustained no casualties.		
291015н	Service Company reports 1 Vietnamese civilian vehicle detonated 40 lb mine. 1 civilian KIA.	BT	038628
311 015H	Company "B" mine sweep team found one 20 lb rock mine, blown in place,	BT	046613

c. Organization and Operations

- (1) Officer Assignments See TAB A, Enclosure (1)
- (2) Operations

1. Oct: Hauled and spread 220 cu.yds. of crushed rock on Route 1 south. Hauled 375 cu.yds. of fill to bridge at AT 918599. Company "B" reports installed water gauges at bridge at BT 031649. Company "D" reports work on 40° bridge at AT 924606 is 60% complete.

Enclosure (1)

2 Oct: The Song Thu Bon Ferry is inoperable due to low water conditions and a sandbar blocking approaches (AT 923535). Spread and graded 280 cu.yds. of crushed rock on QL-1 section II - Dien Ban. 45' of 48" culvert was installed at BT 069565. Tan Giap bridge is 15% complete. Approach repairs to bridge at AT 926606 are 40% complete.

3 Oct: Spread 115 cu.yds. of fill to mine craters on Route 13C. Hauled and spread 190 cu.yds. of crushed rock on QL-1. Company "C" hauled 230 cu.yds. of fill to trash dump near 7th Engr Bn. Continued repair of 40' bridge at AT 924606, project is 85% complete.

4 Oct: Hauled and spread 175 cu.yds. of rock on Route 13C. Spread and graded 215 cu.yds. of crushed rock on QL-1 Section II — Dien Ban. Two towers completed and staged materials for 3 more at 1st MAW. 3rd Bridge Co continued construction of 370° M4T6 fixed span with trestle assemblies across the Cam Lo River YD 146603.

5 Oct: Hauled and spread 1.65 cu.yds. of rock on Route 13C. Spread and graded 210 cu.yds. of crushed rock on QI-1. Company "C" drove piles for headwalls, excavated for foundation, and worked on deadman installation for headwalls at the installation of 75 TPH rock crusher at 7th Engr Bn. Continued work on headwalls on Route 540 south.

6 Oct: Hauled and spread 150 cu.yds. of crushed and shot rock at BT 053594. Lst Bridge Co removed 45% fixed span on QL-1 at BT 052598. 3rd Bridge Co completed installation of the 353484 Cam Lo Bridge at YD 146603.

7 Oct: Hauled and spread 180 cu.yds. of asphalt on QL-1 section II - Dien Ban. Graded portions of Route 540. Bridge at AT 866573 was caved in by a tank. A total of 35 vehicles were moved across the Song Thu Bon Ferry. Repair of the Tam Giap Bridge is 20% complete. Initial preparation for installment of censoring system in the DaNang Barrier was started. Hauled 200 cu.yds. of fill to bridge by-pass at AT 919598.

8 Oct: Hauled and spread 185 cu.yds. of asphalt on section II CL-1. The Song Thu Bon Ferry (AT 923535) is inoperable due to low water. Repairs to 40° bridge at AT 924606 are complete. 60° fixed span bridge at AT 866573 is complete. Installed 21° of culvert at AT 927610. By-pass at Marshall Fridge at AT 919598 is 90% complete.

9 Det: Completed repair of bridge at AT 943695. Spread and graded 120 cu.yds. of rock on QL-1. Repair of the Tam Giap Bridge (BT 055592) is 29% complete. Laying of censoring devices at the DaNang Barrier is 10% complete. 3rd Bridge Co retracted 45% fixed span bridge from An Lo area ND 605310.

10 Oct: Spread and graded 80 sulyds, of crushed rock on QI-1. Installed 2 sections of 48% culvert at Dien Ban. Project is 40% complete. Company "D" made access house for Amtracs at Hill 37.

Il Oct: 1.95 inches of rain was recorded at the 7th Engr Bn during this reporting period. Continued laying censoring devices at the DaNang Barrier. Began laying remaining pipe for water in the installation of the MUST Unit at 1st Hospital Company.

12 Oct: 3.88 inches of rain was recorded in the 7th Engr Bn. Song Thu Bon Ferry continues to be inoperative due to low water conditions. Hauled and spread 200 cu.yds. of 5"(-) rock and 10 cu.mt. of sand for culverts at Dien Ban. 1st Bridge Co staged bridging for construction of a 320! M4T6 floating bridge at AT 961604.

13 Oct: The Song Thu Bon Ferry AT 923535 continues to be inoperative due to sand bar blocking approaches. 1st Bridge Co finished north approach to bridge at AT 961604. Began construction of 320: floating bridge at this location. Began pioneer work on Route LTL 4 from AT 911578 to AT 830559.

14 Oct: 16.38 inches of rain fell on the 7th Engr Bn CP during this reporting period. Song Thu Bon Ferry is inoperative due to swift current of the Song Thu Bon River. Lst Bridge Co laid MO-MAT to stabilize the approach in the construction of M-4/Glass 60 floating bridge at AT 961604. Also hauled 100 crayds, of 5%(-) rock to bridge approach.

15 Oct: 5 inches of rain fell on the 7th Engr Bn CP during this reporting period. Hauled and spread 140 cu.yds. of rock to Route 4. All roads in the 7th Engr Bn area of responsibility were reconned and found to be passable with exception of Route 33. The Song Thu Bon Ferry continues to be inoperative due to the fast flow of the Song Thu Bon River. 3rd Bridge Co installed a 45? fixed span bridge at YD 609312.

16 Oct: 10.73 inches of rain fell on the 7th Engr Bn CP area during this reporting period. 353? fixed apan bridge with trestle assemblies at the Cam Lo River was washed out. Salvage operations have commenced. Installed a 45° fixed span bridge over existing structure at AT 946777. Installed 30° fixed span bridge at AT 919598.

17 Oct: Due to the heavy rains numerous roads and bridges in the DaNang TACR are flooded and impassable. 3.24 inches of rain fell on the 7th Engr Bn CP during this reporting period, Bridge at AT 945695 washed out by heavy flooding. Bridge at AT 957718 washed out by heavy flooding.

18 Oct: The roads in the DaNang TACR continue to be in poor condition as a result of the heavy rains. 3 inches of rain fell on the 7th Engr Bn CP during this reporting period. The Song Thu Bon Ferry is inoperative due to the rapid flow of the Song Thu Bon River. Placed 240 cu₃yds, of 6° rock behind southern abutment for bridge at AT 945694.

19 Oct: 1.38 inches of rain fell on the 7th Engr Bn during this reporting period. Due to the heavy rainfall some of the roads and bridges in the DaNang TACE are closed. Repaired headwalls at the following locations AT 907755 and AT 906762.

20 Oct: The Song Thu Bon Ferry continues to be inoperative due to the rapid current of the Song Thu Bon River. 1.10 inches of rain fell on the 7th Engr Bn CP during the reporting period.

21 Oct: The following bridges were either destroyed, washed out, damaged or flooded, AT 943695, AT 866573. AT 898813, AT 946775, AT 919598, AT 901806, AT 906762, AT 945711 and BT 031648. 1.73 inches of rain fell on the 7th Engr Bn CP during this reporting period.

22 Oct: The Song Thu Bon Ferry is inoperative due to high water and rapid current. Route QL-1 is closed due to Flooding. Assembled 401 of 36" culvert,

23 Oct: Constructed 45' fixed span on Route QL-1 at BT 036633. 1st Bridge Co retrieved 60' fixed span bridge at AT 866574. Hauled and spread 20 cu,yds. of crushed rock to AT 928517.

24 Oct: Song Thu Eon Ferry continues to be inoperative due to high water covering ferry landings. Hauled and placed 30 cu.yds. of 6"(-) rock at bridge approach and turn around on Route 545 at AT 898813. 1st Bridge Company installed anchorage system for 45? fixed span bridge at BT 036634.

25 Oct: Spread and graded 205 cu.yds. of 6" minus rock in washouts on Route QL-1. Installed 201 of 24" culvert at AT 939688. Worked on two culvert headwalls on Route 545. Laid 1,175 sq.ft. of matting at 7th Bulk Fuel Co. 1st Bridge Co began installation of a 1201 fixed span bridge with three transoms at AT 866574.

26 Oct: Spread and graded 200 cu.yds. of rock on Route 13C. Hauled and spread 14O cu.yds. of fill on QL-1-Dien Ban. Began removing curbing, hand rails, and decking form first 5 spans on west side of bridge at AT 031649. Continued laying M8A1 matting at 7th Bulk Fuel Co.

27 Oct: Hauled and spread 108 cu.yds. of rock on Route 13C. Sont Thu Bon Ferry is inoperative due to the high water level of the Song Thu Bon River. Laid a total of 8,685 sq.ft. to this date. Hauled 30 cu.y ds. of rock to south ferry landing at AT 923535.

28 Oct: Hauled and spread 312 cu.yds. of 6" minus rock on north approach to bridge at AT 898813. Hauled and spread 125 cu.yds. of fill on approach to bridge at AT 866574. Graded Route 540. 1st Bridge Co constructed overhead cable system at Cooper Ferry at BT 031649.

29 Oct: Hauled and spread 276 cu.yds. of rock on Route 13C. Hauled and spread 365 cu.yds. of 5"(-) rock on Route QL-1. Spread 8 tons of asphalt on Route QL-1B. Hauled and spread 190 cu.yds. of fill on Route 540. Installed and tested two seismic devices on the DaNang Barrier. Graded berms for 7th Bulk Fuel Co.

30 Octo Spread and compacted 150 cu.yds, of rock on Route CL-1. Hauled and spread 250 cu.yds. of fill on Route 540. Hauled and spread 276 cu.yds. of crushed rock on Route 130. Made minor repairs to bridge at AT 915731. Constructed 5 float reinforced ferry at BT 031649.

31 Oct: Song Thu Bon Ferry completed 22 round trips.
Assembled 4 30: culverts on Route QL-1. Installed 5,984 sq.ft. of M8Al around road and installed temporary drainage at the 7th Bulk Fuel Co.
1st Bridge Co completed 5 float reinforced ferry at BT 031649. 1st Bridge Co removed 45: fixed span bridge at AT 941785.

d. Plans

- (1) Continue general support of all units within the 1st Marine Division TAOR, or assigned by III MAF Headquarters.
- (2) Continue support of CAG units within 1st Marine Division TAOR, or as assigned by III MAF Headquarters.
- (3) Continue maintenace of Bridges within 1st Marine Division TAOR, or as directed by III MAY Headquarters.
 - (4) Continue upgrading of Rowie 1,
 - (5) Continue upgrading of Route 130.
 - (6) Continue upgrading of Route 545.
 - (7) Continue upgrading of Route 30.
 - (8) Continue maintenance of Route 540 to An Hoa.
 - (9) Continue construction of DaNang Wire Barrier.

e. Training

- (1) Command indoctrination and information for newly arrived personnel and debriefing for those departing.
 - (2) I enlisted attended Embark School. (Division)
 - (3) 3 enlisted, 1 officer attended Basic Supply Accounting. (FLC)
 - (4) 1 enlisted, 2 efficers attended Embark School, (Okinawa)
 - (5) 2 enlished attended Infantry Weapons Repair Course. (Okinawa)
 - (6) I enlisted attended Ammo Tech School. (Ckinawa)
- (7) I officer, I SNCO and I enlisted attended Division Leadership Course, (Division)
 - (8) I enlisted attended Projectionist School. (III MAF)
 - (9) I enlisted attended Fiscal Clerk School. (Division)
 - f. Logistics, Equipment and Supply
 - (1) Administration

October

- 4 Preparation were made for MARES/FORSTAT
- 10 Received eight (8) Truck, Dump. These Trucks were force feed.
- Received one (1) MRS-200 Tractor, that was invoiced from 9th Engr Bn, to 7th Engr Bn.
- 19 Picked up secondary unit for 75 ton Rock Crusher.
- Received thirteen (13) M23A1C 10 ton Truck, Tractor. Rate fourteen (14) by T/E, still one (1) short.
- 27 lst Bridge Company received one (1) M123A1C 10 ton Truck, Tractor rate by T/E.

(2) Supply

7th Engineer Battalion FMF (AC 21300)

During the month of October the Battalion Supply Section processed 148 priority 02 and 1,041 priority 05 requisitions and 289 priority 12 and 17 requisitions. Also processed were 957 receipts from due, 348 issues from due and 289 issues from warehouse.

1st Bridge Company FMF (AC 21325)

During the month of October 1st Bridge Company Supply Section processed 352 requisitions. Also processed were 126 receipts from due, 126 issues from due and 33 issues from warehouse,

Motor Transport

Approximately 102,030 miles were logged on the Battalion's Motor transport Vehicles during October.

Maintenance

The Battalion Maintenance Plateon completed 71 Meter Transport work orders during the month of October. A total of 119 work orders were submitted, 21 were sent to maintenance Battalion. Total work orders for Engineer Equipment numbered 86 with 51 completed and 8 were sent to FSR.

Messing

The Battalion Mess Staff continued to provide four meals daily except on Sunday; the fourth meal being a midnight ration for night crews. On Sunday a brunch replaces breakfast and dinner.

Medical

The Battalion Aid Station treated 1,114 military and 157 Vietnamese. During the month of October the Dental Clinic treated 312 military and 110 Vietnamese.

g. Civil Affairs/Civic Action

- (1) The Civic Action Program continues on a daily basis.
- (2) Activities were as follows:
- (a) The MedCap Program provided treatment for two hundred sixty five persons.
- (b) The Battalion sponsored, Vietnamese brickyard produced a total of 28,700 soil-cement bricks during this period.
- (c) A total of 14,500 soil-cement bricks were issued for various Civic Action projects throughout Quang Nam Province.
 - (d) 6 bunkers in An Ngai Tay hamlet are 90% complete.
 - (e) A two-room school in Tung Son is 30% complete.
 - (f) A head in Tung Son is 15% complete.
 - (g) 3 bath houses in Tung Son are 75% complete.
 - (h) A head in Tung Son is 15% complete.
- (i) A plow and spiked-tooth harrow were given to the farmers of An Ngai Tay hamlet,
- (j) 3 garden plots were started in Hoa Thanh Village and Hoa Ninh Refugee camp utilizing American seeds and methods.
 - (k) A defensive perimeter in An Ngai Dong is 10% complete.
 - (1) A hand-type water pump was installed in Tung Son Hamlet.

PART IV

SUPPORTING DOCUMENTS

1. Officer Assignments, See TAB A of enclosure (1).



1/EAH/prm 31. Oct 1968

NA ME	Serv.no./MCC	RA NK	PRIMARY DUTY	RTD
	China	1000000000	TICTIBILE DOLL	IL III
A MNAS, T.T.	053496/1302/0430	LtCol	BnCmdr	30Aug69
HOOK, R.A. AOYAMA,K.M.	060121/1302/0302 0103117/1302	Мај	Execo	20Nov69
DICKEN D.T.	0104170/1302	lstLt 2ndLt	CivAffOff Asst S-3/OK Rock	28Apr69
·	01041 Of 150E	211(1.11)	Crusher	228 ugos
FRANKE, P.A.	0104858/2501	2ndLt	CommO	8Sep69 '
FRARTZ JUD .	095726/1302	1stLt	S-2	24Mer69
HAMILTON, G.S.	072022/1302	Maj	S	11 ട ൂ69
HILLARD, A.S.	094276/3302	LstLt	HqCoCmdr	2Feb69
HUFNAGEL 3E .A . INLLEY .M .G .	079266/0130 078896/1302/5702	CW O⊷⊙	S-1/Adj/Leg0	lJan69
MORIAN, L.E.	01.03700/1302	Capt IstLt	S-3 Asst S-3/ConstO	7Jul69 9Mar69
REID G.H.	025009/1302	1stLt	Asst Sal	hFeb69
-			111,150 50-2	2200007
SERVICE COMPANY				
WITMER, U.V.	095166/1302/1320	lstLt	co	9May59
Barber, J.S. Felty, D.W. Jr.	096 092/3 010/3502	lstlt	Exec	16Dec68
GOCOE of old	- 098649/2.310 - 0102777/3502 -	CWO=2 Le tLt	MainPltCmdr	1.3Dec 68
HAMACK J.A.	070f885/3201	2ndIt.	BnMTO Utilo	21Apr69 13Sep69
KRUSEMARY, L.E.	0104657/3002	2ndLt	BnSup0	120:t69
-				.a. 00 00 j
"A" COMPANY	2221677222			
MORRISON, A.E. LONG, R.L.	097465/1302 01020914/1302	lstIt	go	18Dec68
CARLSON, F.G.	0105884/1301	lstLt 2ndLt	Exec PltCmdr	13Dec68
CRAM A .B.	01.03164/1302	lstLt	PltCmdr	230ct69 NApr69
FIAMM NG .J. N.	0105512/1301	2ndLt	EquipPltCmdr	170:t69
RIMEHART, C.S.	0105243/1301	2mallt	PltCmdr	30Sep69
18D U. C. OMEDA NIV		٠		
ESPOSITO, M.J.	093085/1302/1320	r1		
MICK E.W.	0100510/1302	Capt LstLt	CO Exe c	7Feb69
ADAMS R.E.	0105141/1301	2ndLt	PltCmdr	25 Juné 9 23 Octé 9
erickšon, r. l.	0105033/1301	2nd Lt	PltCmdr	30Sep69
JACKSON, J.M.	0988511/1310	CHO-3	EquipPltCmdr	29Aug69
JONES, J.C.	01.05555/1301	2ndLt	PltCmdr	230ct69
FOR COMPANY				•
MARSHALL, J. P.	080929/1302/1310	Capt	CO	30ct69
KRUCER, L.W.	01.02065/1302	1stLt	Exec	23Dec69
BROOKS, J.D.	01081.87/1301	2nd.Lt	EquipPliCmdr	
DEBUSSEY,R.C.	01.04910/1301	2ndLt	PltCmdr	2Dec68 23Nov69
GETTMAN, J.A. SOKOLOWSKI, T.E.	0102613/1302 0104779/1302	lstīt	FltCmdr	3 Jun 69
WILLS, H. J.	0106074/1301	2ndLt 2ndLt	Pl.tCmdr	18Aug69
	-moo of the moon	and into	PltCmdr	23Nov69

DECLASSIFIED

-						.*
	NA ME IIDII COMPA NY	SERV.NO.	RANK	PRIMARY DUTY	RTD	
	BOTELHO,E. GARRIDO,D.D. BRISSON,J.J. LEONARD.R.L. LINDSEY,E.E. WHITE,E.G.	096213/1302 0101081/1302 0105725/1310 0105165/1301 0105959/1301 0105701/1501	lstIt lstIt WO 2ndIt 2ndIt 2ndIt	CO Exec PltCmdr PltCmdr PltCmdr PltCmdr	18Sep69 29Jun69 1Aug69 29Sep69 23Nov69 17Oct69	
-	lst BRIDGE COMPA	.NY			2	
4 di •	Frasenell ₉ d.A. Iageman ₃ r.C.	094979/1302 0101216/1302	istIt lstIt	CO PltCmdr	1.80ec68 55ep69	- 2
	BECKER, M. L. GORDON, T.E. OSBECK, D.G. TORBET, P.A. UNGERN, R.F. N.	0305366/1301 0305524/1301 0106007/2301 0104365/3002 0102352/1302	2ndLt 2ndLt 2ndLt 2ndLt 2ndLt LstLt	PitCmdr PitCmdr MaintPitCmdr SupO PitCmir	23Nov69 24O: t69 23Nov69 16Sep69 1.2Dec68	
	USN examples				•	
· ·	MOKENMIH, E. III. COLEMAN, G.B.	728369/2105 723325/43.05	Lt Ls	BnSurgeon BnChaplain	223u169 24Ju169	
	-		=		• • ' .	